

ISO-Designer

Version Update from V. 5.2.0 to V. 5.2.1

Jetter AG Graeterstrasse 2 71642 Ludwigsburg, Germany

Phone:

Headquarters +49 7141 2550-0 Sales +49 7141 2550-531 Technical hotline +49 7141 2550-444

E-mail:

Hotline hotline@jetter
Sales vertrieb@jetter

Revision 1.00

7/27/2017

This document has been compiled by Jetter AG with due diligence based on the state of the art as known to them. Any revisions and technical advancements of our products are not automatically made available in a revised document. Jetter AG shall not be liable for any errors either in form or content, or for any missing updates, as well as for any damage or detriment resulting from such failure.

Table of Contents

	2
1 New features	
1.1 Objects	
1.1.1 Color depth support of PNG graphic files in ISO-Designer	
2 Fixed software bugs	2
2.1 Miscellaneous	2
2.1.1 Save All created unnecessary registry nodes	2
2.2 Resource files	2
2.2.1 ISO-Designer chrashed when importing standard resource files	2

Jetter AG New features

1 New features

Below, all features that are new in this version, as well as the enhancements are listed.

1.1 Objects

1.1.1 Color depth support of PNG graphic files in ISO-Designer

Now, ISO-Designer supports PNG objects with more than 256 colors (8 bits per pixel). Possible values are 24 bits or 32 bits depending on the image file.

Fixed software bugs Jetter AG

2 Fixed software bugs

This chapter describes the software bugs which have been fixed in the new software release.

2.1 Miscellaneous

2.1.1 Save All created unnecessary registry nodes

Save All created unnecessary registry nodes which survived when JetViewSoft was closed.

2.2 Resource files

2.2.1 ISO-Designer chrashed when importing standard resource files

This bug was fixed.